

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours:

842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings:

1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 SERVICING (1)	DRAIN FUEL TANK IF HELICOPTER IS PARKED MORE THAN 7 DAYS	7d	833.40h/ 1,237.00C/ 06-24-2015	07-01-2015	420dayOVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 AIR CONDITIONING (1)	ACCOMPLISH VISUAL INSPECTION OF AIR CONDITIONING COMPRESSOR BRACKET FOR CRACKS	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 AIR CONDITIONING (2)	CHECK TENSION AND INSPECT CONDITION OF THE AIR CONDITIONING COMPRESSOR FOR CRACKS	400.00H	728.80h/ 08-02-2013	1,128.80h	286.10h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 AIR CONDITIONING (3)	REPLACE COMPRESSOR DRIVE BELT	1,600.00H 3y		1,600.00h	757.30h	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 ELECTRICAL POWER (2)	FOR SAFT BATTERY: INSPECT BATTERY	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 ELECTRICAL POWER (3)	INSPECT OVERHEAD PANEL	2,400.00H		2,400.00h	1,557.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 EQUIPMENT / FURNISHINGS (1)	CHECK BATTERY VOLTAGE IN UNDERWATER EMERGENCY LOCATOR TRANSMITTER	24m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2017	10month	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 EQUIPMENT / FURNISHINGS (2)	INSPECT ELT AND ELT CONTROL UNIT	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 FIRE PROTECTION SYSTEM (1)	FOR PORTABLE FIRE EXTRINGUISHER FROM THE MANUFACTURE TOTAL FEUERSCHUTZ GMBH: INSPECT POTABLE FIRE EXTRINGUISHER	2y	06-24-2015	06-24-2017	.83year	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 FIRE PROTECTION SYSTEM (2)	ACCOMPLISH FOLLOW-UP CHECK OF PORTABLE FIRE EXTRINGUISHER (CONTAINER HYDROSTATIC PRESSURE TEST)	10y	11-01-2007	11-01-2017	1.19year	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 FIRE PROTECTION SYSTEM (4)	CHECK WEIGHT OF ENGINE FIRE EXTRINGUISHER BOTTLE	5y	11-01-2012	11-01-2017	1.19year	MSM

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours:

842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings:

1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		0632	05/16/2016	MSM 05-25-00 INDICATING AND RECORDING SYSTEMS (2)	PERFORM FUNCTIONAL TEST OF FAN IN THE PELICAN RACK	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 INDICATING AND RECORDING SYSTEMS (3)	PERFORM FUNCTIONAL TEST OF THE CPDS FAN	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 NAVIGATION (1)	PERFORM 6 MONTH FUNCTIONAL CHECK OF EMERGENCY POWER SUPPLY BATTERY	6m	833.40h/ 1,237.00C/ 06-24-2015	12-24-2015	8monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 NAVIGATION (2)	INSPECT EMERGENCY POWER SUPPLY BATTERY IAW THE MANUFACTURERS INSTRUCTIONS EVERY 12 MONTHS	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 NAVIGATION (3)	INSPECT AVIONICS EQUIPMENT EVERY 12 MONTHS	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 NAVIGATION (4)	PERFORM LEAKAGE TEST OF PITOT-STATIC SYSTEM	24m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2017	10month	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 NAVIGATION (5)	ACCOMPLISH 24 MONTH INSPECTION OF DISPLAY ACCURACY OF PITOT-STATIC SYSTEM	24m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2017	10month	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 NAVIGATION (6)	PERFORM 12 MONTH FUNCTIONAL TEST OF AIR DATA SYSTEM ADS 3000 /3200	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 NAVIGATION (7)	12 MONTH COMPENSATE ATTITUDE AND HEADING REFERENCE SYSTEM AHRS	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 NAVIGATION (8)	12 MONTH COMPENSATE STANDBY COMPASS	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours:

842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings:

1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 NAVIGATION (9)	12 MONTH COMPENSATE GYRO COMPASS SYSTEM	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 DOORS AND SERVICE COVERS (1)	VISUAL INSPECTION OF THE SLIDING DOOR UPPER ARM FOR CRACKS	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 FUSELAGE (1)	FITTING OF MAIN TRANSMISSION MOUNTS (INSPECTION P/N L533M2001102) FOR CRACKS	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 WINDOWS (1)	REMOVE PRESS-OUT SIDE WINDOW PANES, INSPECT AND INSTALL	2y	833.40h/ 1,237.00C/ 06-24-2015	06-24-2017	.83year	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 WINDOWS (2)	REMOVE AND PRESS-OUT SLIDING DOOR WINDOW PANES, INSPECT AND INSTALL	2y	833.40h/ 1,237.00C/ 06-24-2015	06-24-2017	.83year	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (2)	INSPECT MAIN ROTOR HUB-SHAFT FOR CRACKS (INTERVAL DEPENDS ON THE TEST PROCEDURE)	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (3)	PERFORM VISUAL INSPECTION OF ADAPTER FOR DISCHARGER FOR CRACKS AND CORROSION	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (5)	INSPECT PU PROTECTIVE FOIL FOR ROUGHNESS, LOOSENESS OR SEPARATION	50.00H		50.00h	792.70h/ OVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (6)	REMOVE MAIN ROTOR HUB-SHAFT AND INSPECT	4,000.00H		4,000.00h	3,157.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (7)	REMOVE SWASHPLATE, DISASSEMBLE AND INSPECT	4,000.00H		4,000.00h	3,157.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (8)	CHECK ROLLING FRICTION OF THE SWASHPLATE BEARINGS	4,000.00H		4,000.00h	3,157.30h	MSM

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (9)	INSPECT TORSION SLIPPAGE MARKS ON BOLT HEADS OF ATTACHMENT HARDWARE OF ROTATING CONTROL RODS	50.00H		50.00h	792.70h/ OVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (10)	REMOVE DRIVING UNIT, DISASSEMBLE AND INSPECT	4,000.00H		4,000.00h	3,157.30h	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 MAIN ROTOR SYSTEM (11)	INSPECTION SWASHPLATE BEARING	50.00H 6m		50.00h	792.70h/ OVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR DRIVE (1)	RETIGHTEN MAIN ROTOR HUB-SHAFT NUT TO THE SPECIFIED TORQUE	1,000.00H		1,000.00h	157.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR DRIVE (2)	REMOVE DRIVE SHAFTS AND INSPECT	4,800.00H 6y		4,800.00h	3,957.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR DRIVE (3)	HAVE DRIVE SHAFTS INSPECTED BY THE MANUFACTURER	5,600.00H 9y		5,600.00h	4,757.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR DRIVE (4)	REMOVE SPACER TUBE AND INSPECT	1,600.00H		1,600.00h	757.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR DRIVE (6)	MAIN TRANSMISSION: HAVE MAIN TRANSMISSION INSPECTED BY THE MANUFACTURER (INTERMEDIATE INSPECTION)	4,000.00H		4,000.00h	3,157.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR DRIVE (7)	INSPECT DRIVE STAGE AND BEVEL GEAR	2,400.00H		2,400.00h	1,557.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 MAIN ROTOR DRIVE (8)	HAVE MAIN TRANSMISSION INSPECTED BY MANUFACTURE (INTERMEDIATE INSPECTION)	2,400.00H		2,400.00h	1,557.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 TAIL ROTOR SYSTEM (1)	REMOVE RAIL ROTOR, DISASSEMBLE AND INSPECT	1,600.00H 4y		1,600.00h	757.30h	MSM

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		0632	05/16/2016	MSM 05-25-00 TAIL ROTOR DRIVE (1)	CHECK RADIAL DEFLECTION OF THE TAIL ROTOR DRIVE SHAFT	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 TAIL ROTOR DRIVE (2)	REMOVE TAIL ROTOR DRIVE SHAFTS, DISASSEMBLE AND INSPECT	4,000.00H		4,000.00h	3,157.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 TAIL ROTOR DRIVE (3)	DO THE INSPECTION OF THE INPUT DRIVE FLANGE	1,200.00H 3y	833.40h/ 1,237.00C/ 06-24-2015	2,033.40h/ 06-24-2018	1,190.70h/ 1.83year	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 TAIL ROTOR DRIVE (4)	INSPECT TAIL ROTOR TRANSMISSION	1,600.00H 4y	833.40h/ 1,237.00C/ 06-24-2015	2,433.40h/ 06-24-2019	1,590.70h/ 2.83year	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 ROTOR FLIGHT CONTROLS (1)	ADJUST THE BOOSTED SECTION OF THE TAIL ROTOR CONTROLS	4,000.00H		4,000.00h	3,157.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 ROTOR FLIGHT CONTROLS (2)	REMOVE MIXING LEVER GEAR UNIT, DISASSEMBLE AND INSPECT	4,000.00H		4,000.00h	3,157.30h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 ROTOR FLIGHT CONTROLS (3)	DISASSEMBLE PEDALS OF THE TAIL ROTOR CONTROLS AND INSPECT	50.00H	833.40h/ 1,237.00C/ 06-24-2015	883.40h	40.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 ROTOR FLIGHT CONTROLS (4)	INSPECT CONTROL ROD OF THE TAIL ROTOR CONTROLS	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 ROTOR FLIGHT CONTROLS (5)	INSPECT BALL PIVOT ON THE TAIL ROTOR CONTROLS	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 ROTOR FLIGHT CONTROLS (6)	INSPECT BALL PIVOT ON THE TAIL ROTOR CONTROLS	400.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	1,233.40h/ 06-24-2016	390.70h/ 2monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 OIL SYSTEM	INSPECT ENGINE FUZZ BURNER SYSTEM	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	MSM

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours:

842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings:

1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY	Now	0632	05/16/2016	MSM 05-25-00 OPTIONAL EQUIPMENT (1)	REMOVE AUXILIARY FUEL TANK AND INSPECT	500.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	1,333.40h/ 06-24-2016	490.70h/ 2monthOVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 OPTIONAL EQUIPMENT (2)	REMOVE AUXILIARY FUEL TANK AND INSPECT BLADDER TANK	5y	833.40h/ 1,237.00C/ 06-24-2015	06-24-2020	3.83year	MSM
MANDATORY		0632	05/16/2016	MSM 05-25-00 OPTIONAL EQUIPMENT (14)	INSPECT ROTOR BRAKE SYSTEM	100.00H	833.40h/ 1,237.00C/ 06-24-2015	933.40h	90.70h	MSM
MANDATORY	Now	0632	05/16/2016	12 MONTH INSPECTION 05-23-00	12 MONTH	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	INSPECTION
MANDATORY		130100 2692	05/18/2016	130100 (Desc: FUEL-PUMP-CARTRI DGE) - (SN#: 2692) :	FUEL PUMP- TBO	5,000.00H		5,000.00h	4,157.30h	OVERHAUL
MANDATORY		130100 2995	05/18/2016	130100 (Desc: FUEL-PUMP-CARTRI DGE) - (SN#: 2995) :	FUEL PUMP- TBO	5,000.00H		5,000.00h	4,157.30h	OVERHAUL
MANDATORY		130100 2998	05/18/2016	130100 (Desc: FUEL-PUMP-CARTRI DGE) - (SN#: 2998) :	FUEL PUMP- TBO	5,000.00H		5,000.00h	4,157.30h	OVERHAUL
MANDATORY		130100 3131	05/18/2016	130100 (Desc: FUEL-PUMP-CARTRI DGE) - (SN#: 3131) :	FUEL PUMP- TBO	5,000.00H		5,000.00h	4,157.30h	OVERHAUL
MANDATORY		23081-073 P2204	10/01/2007	23081-073 (Desc: STARTER-GENERAT OR (200A)) - (SN#: P2204) : STARTER GENERATOR OH	OVERHAUL	1,000.00H		1,000.00h	157.30h	OVERHAUL

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		23081-073 P2212	10/01/2007	23081-073 (Desc: STARTER-GENERAT OR (200A)) - (SN#: P2212) : STARTER GENERATOR OH	OVERHAUL	1,000.00H		1,000.00h	157.30h	OVERHAUL
MANDATORY		4649010010 1351	05/17/2016	4649010010 (Desc: MAIN GEARBOX) - (SN#: 1351) : MAIN TRANS.	OVERHAUL	4,000.00H		4,000.00h	3,157.30h	OVERHAUL
OPTIONAL		4649201018 1551	05/17/2016	4649201018 (Desc: TRANSMISSION COVER) - (SN#: 1551) : ON CONDITION	ON CONDITION	0m				ON CONDITION
MANDATORY		4649201018 1551	05/17/2016	4649201018 (Desc: TRANSMISSION COVER) - (SN#: 1551) : TRANSMISSION COVER	RETIRE	14,000.00H		14,000.00h	13,157.30h	RETIRE
MANDATORY		4649301034 1136	05/17/2016	4649301034 (Desc: UPPER HOUSING) - (SN#: 1136) : UPPER HOUSING	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
MANDATORY		4649301064 1140	05/17/2016	4649301064 (Desc: LOWER HOUSING) - (SN#: 1140) : LOWER HOUSING	RETIRE	12,600.00H		12,600.00h	11,757.30h	RETIRE
MANDATORY		4649302041 2131	05/17/2016	4649302041 (Desc: INPUT PINION) - (SN#: 2131) : INPUT PINION	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours:

842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings:

1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		4649302041 2141	05/17/2016	4649302041 (Desc: INPUT PINION) - (SN#: 2141) : INPUT PINION	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		4649303030 2218	05/17/2016	4649303030 (Desc: INTERMEDIATE SHAFT) - (SN#: 2218) : INTERMEDIATE SHAFT	RETIRE	16,000.00H		16,000.00h	15,157.30h	RETIRE
MANDATORY		4649303030 2266	05/17/2016	4649303030 (Desc: INTERMEDIATE SHAFT) - (SN#: 2266) : INTERMEDIATE SHAFT	RETIRE	16,000.00H		16,000.00h	15,157.30h	RETIRE
MANDATORY		4649303034 1984	05/17/2016	4649303034 (Desc: BEVEL GEAR) - (SN#: 1984) : BEVEL GEAR	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
MANDATORY		4649303034 2048	05/17/2016	4649303034 (Desc: BEVEL GEAR) - (SN#: 2048) : BEVEL GEAR	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
MANDATORY		4649304044 926	05/17/2016	4649304044 (Desc: COLLECTIVE SHAFT) - (SN#: 926) : COLLECTIVE EC135	RETIRE	18,000.00H		18,000.00h	17,157.30h	RETIRE
MANDATORY		4649304045 1071	05/17/2016	4649304045 (Desc: COLLECTIVE WHEEL) - (SN#: 1071) : COLLECTIVE EC135	RETIRE	18,000.00H		18,000.00h	17,157.30h	RETIRE

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		4649305034 1288	05/17/2016	4649305034 (Desc: SUPPORT TUBE) - (SN#: 1288) : SUPPORT TUBE	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		4649306094 689	05/17/2016	4649306094 (Desc: PINION) - (SN#: 689) : PINION EC135	RETIRE	8,000.00H		8,000.00h	7,157.30h	RETIRE
MANDATORY		4649306095 759	05/17/2016	4649306095 (Desc: PINION SHAFT) - (SN#: 759) : PINION SHAFT EC135	RETIRE	8,000.00H		8,000.00h	7,157.30h	RETIRE
MANDATORY	Now	0632	05/16/2016	AD 2016-11-21	REDUCING LIFE LIMIT ON CERTAIN PARTS AND REMOVING EACH PART THAT HAS REACHED ITS LIFE LIMIT	07/11/2016		07-11-2016	44dayOVD	AD
MANDATORY		0632	05/16/2016	AD2013-21-05	TAIL ROTOR LINEAR TRANSDUCER BEARING INSPECTION	800.00H	833.40h/ 1,237.00C/ 06-24-2015	1,633.40h	790.70h	AD
MANDATORY	Now	0632	05/16/2016	AD2014-05-01	MGB OIL SAMPLE	100.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	933.40h/ 06-24-2016	90.70h/ 2monthOVD	AD
MANDATORY	Now	0632	05/16/2016	AD2014-05-06	INSPECT FLIGHT CONTROL LEVER BEARINGS	800.00H 36m		800.00h	42.70h/ OVD	AD
MANDATORY		0632	05/16/2016	AD2014-16-24	VISUAL INSPECTION OF M/R HUB FOR CRACKS	50.00H	833.40h/ 1,237.00C/ 06-24-2015	883.40h	40.70h	AD
MANDATORY	Now	0632	05/16/2016	ICA - 100 HR // 12 MO AVIONICS INSTALLATION INSPECTION	100 HR // 12 MO AVIONICS INSTALLATION INSPECTION IAW FAR 43 APPENDIX D	100.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	933.40h/ 06-24-2016	90.70h/ 2monthOVD	ICA
MANDATORY	Now	0632	05/16/2016	ICA - 12 MO ELT INSTALLATION INSPECTION	12 MO ELT INSTALLATION INSPECTION IAW FAR 91.207	12m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2016	2monthOVD	ICA

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY	Now	0632	05/16/2016	ICA- FDC / AEROFILTER INLET BARRIER FILTER INSPECTION	100 HOUR // 12 MONTH FDC / AEROFILTER INLET BARRIER FILTER INSPECTION	100.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	933.40h/ 06-24-2016	90.70h/ 2monthOVD	ICA
MANDATORY		0632	05/16/2016	ICA- FDC / AEROFILTER INLET BARRIER FILTER RETIREMENT	4500 HOUR FDC / AEROFILTER INLET BARRIER FILTER RETIREMENT	4,500.00H		4,500.00h	3,657.30h	ICA
MANDATORY		0632	05/16/2016	INTERMEDIATE INSPECTION 05-22-00	500 HR INSPECTION	500.00H	728.80h/ 08-02-2013	1,228.80h	386.10h	INSPECTION
MANDATORY		L290M20A1014 01391	05/18/2016	L290M20A1014 (Desc: HYDRAULIC PUMP) - (SN#: 01391) : HYDRAULIC PUMP	OVERHAUL	7,500.00H		7,500.00h	6,657.30h	OVERHAUL
MANDATORY		L290M20A1014 01398	05/18/2016	L290M20A1014 (Desc: HYDRAULIC PUMP) - (SN#: 01398) : HYDRAULIC PUMP	OVERHAUL	7,500.00H		7,500.00h	6,657.30h	OVERHAUL
MANDATORY		L621M1010056 3170	05/17/2016	L621M1010056 (Desc: ROTOR BLADE ASSY) - (SN#: 3170) : MAIN ROTOR BLADE EC135	RETIRE	12,400.00H		12,400.00h	11,557.30h	RETIRE
MANDATORY		L621M1010056 3211	05/17/2016	L621M1010056 (Desc: ROTOR BLADE ASSY) - (SN#: 3211) : MAIN ROTOR BLADE EC135	RETIRE	12,400.00H		12,400.00h	11,557.30h	RETIRE
MANDATORY		L621M1010056 3244	05/17/2016	L621M1010056 (Desc: ROTOR BLADE ASSY) - (SN#: 3244) : MAIN ROTOR BLADE EC135	RETIRE	12,400.00H		12,400.00h	11,557.30h	RETIRE

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		L621M1010056 3275	05/17/2016	L621M1010056 (Desc: ROTOR BLADE ASSY) - (SN#: 3275) : MAIN ROTOR BLADE EC135	RETIRE	12,400.00H		12,400.00h	11,557.30h	RETIRE
MANDATORY		L623M2001213 05-0251N	05/17/2016	L623M2001213 (Desc: RING) - (SN#: 05-0251N) : RING	RETIRE	8,000.00H		8,000.00h	7,157.30h	RETIRE
MANDATORY		L623M2001214 05-0251N	05/17/2016	L623M2001214 (Desc: RING) - (SN#: 05-0251N) : RING	RETIRE	8,000.00H		8,000.00h	7,157.30h	RETIRE
OPTIONAL		L623M2005103 05-0251Z	05/17/2016	L623M2005103 (Desc: SWASH PLATE) - (SN#: 05-0251Z) : ON CONDITION	ON CONDITION	0m				ON CONDITION
MANDATORY		L623M2005205 436	05/17/2016	L623M2005205 (Desc: CARDAN RING) - (SN#: 436) : CARDAN RING	RETIRE	12,900.00H		12,900.00h	12,057.30h	RETIRE
MANDATORY		L623M2006213 05-1031	05/17/2016	L623M2006213 (Desc: BOLT) - (SN#: 05-1031) : BOLT SLIDING SLEEVE	RETIRE	12,900.00H		12,900.00h	12,057.30h	RETIRE
MANDATORY		L623M2006213 05-1079	05/17/2016	L623M2006213 (Desc: BOLT) - (SN#: 05-1079) : BOLT SLIDING SLEEVE	RETIRE	12,900.00H		12,900.00h	12,057.30h	RETIRE
OPTIONAL		L642A0101052 M1665	05/17/2016	L642A0101052 (Desc: TRH) - (SN#: M1665) : ON CONDITION	ON CONDITION	0m				ON CONDITION

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		L642A2002101 M7893	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7893) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M7928	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7928) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M7932	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7932) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M7935	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7935) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M7939	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7939) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M7944	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7944) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M7959	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7959) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		L642A2002101 M7972	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7972) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M7994	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M7994) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2002101 M8000	05/17/2016	L642A2002101 (Desc: BLADE ASSY) - (SN#: M8000) : TAIL ROTOR BLADE EC135	RETIRE	12,000.00H		12,000.00h	11,157.30h	RETIRE
MANDATORY		L642A2019201 FR255	05/17/2016	L642A2019201 (Desc: FLANGE, SPLINED) - (SN#: FR255) : SPLINED HUB	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
MANDATORY		L651M1008215 0632	05/17/2016	L651M1008215 (Desc: RUBBER SLEEVE) : RUBBER SLEEVE	RETIRE	60m				RETIRE
MANDATORY		L651M1008215 0632	05/17/2016	L651M1008215 (Desc: RUBBER SLEEVE) : RUBBER SLEEVE	RETIRE	60m				RETIRE
MANDATORY		L651M1008215 0632	05/17/2016	L651M1008215 (Desc: RUBBER SLEEVE) : RUBBER SLEEVE	RETIRE	60m				RETIRE
MANDATORY		L651M1008215 0632	05/17/2016	L651M1008215 (Desc: RUBBER SLEEVE) : RUBBER SLEEVE	RETIRE	60m				RETIRE
MANDATORY		L651M1008215 0632	05/17/2016	L651M1008215 (Desc: RUBBER SLEEVE) : RUBBER SLEEVE	RETIRE	60m				RETIRE

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		L651M1008215 0632	05/17/2016	L651M1008215 (Desc: RUBBER SLEEVE) ; RUBBER SLEEVE	RETIRE	60m				RETIRE
MANDATORY		L651M2005203 1423	05/17/2016	L651M2005203 (Desc: TUBE WELDED) - (SN#: 1423) : TUBE	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
OPTIONAL		L651M2008101 05-1423	05/17/2016	L651M2008101 (Desc: SHAFT LONG ASSY.) - (SN#: 05-1423) : ON CONDITION	ON CONDITION	0m				ON CONDITION
MANDATORY		L651M2008220 1462	05/17/2016	L651M2008220 (Desc: COUPLING FLANGE) - (SN#: 1462) : COUPLING FLANGE	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
MANDATORY		L651M2008220 1470	05/17/2016	L651M2008220 (Desc: COUPLING FLANGE) - (SN#: 1470) : COUPLING FLANGE	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
MANDATORY		L652A0101052 M2664	05/18/2016	L652A0101052 (Desc: TR XMSN/ TGB) - (SN#: M2664) : T/R TRANSMISSION EC135 P2	OVERHAUL	3,600.00H		3,600.00h	2,757.30h	OVERHAUL
MANDATORY		L652A1002601 M749	05/18/2016	L652A1002601 (Desc: INPUT GEAR WHEEL) - (SN#: M749) : INPUT GEAR WHEEL	RETIRE	8,000.00H		8,000.00h	7,157.30h	RETIRE
MANDATORY		L652A1003601 M730	05/18/2016	L652A1003601 (Desc: OUTPUT GEAR WHEEL) - (SN#: M730) : OUTPUT GEAR WHEEL	RETIRE	11,000.00H		11,000.00h	10,157.30h	RETIRE

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours:

842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings:

1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		L652A2006203 SP378	05/18/2016	L652A2006203 (Desc: INPUT FLANGE) - (SN#: SP378) : INPUT DRIVE FLANGE	RETIRE	20,000.00H		20,000.00h	19,157.30h	RETIRE
MANDATORY		L671M3009206 CN05/7101	05/18/2016	L671M3009206 (Desc: CONTROL ROD) - (SN#: CN05/7101) : CONTROL ROD	CONTROL ROD	19,200.00H		19,200.00h	18,357.30h	RETIRE
MANDATORY		L671M3009206 CN05/7101*	05/18/2016	L671M3009206 (Desc: CONTROL ROD) - (SN#: CN05/7101*) : CONTROL ROD	CONTROL ROD	19,200.00H		19,200.00h	18,357.30h	RETIRE
MANDATORY		L671M3009206 CN05/7101**	05/18/2016	L671M3009206 (Desc: CONTROL ROD) - (SN#: CN05/7101**) : CONTROL ROD	CONTROL ROD	19,200.00H		19,200.00h	18,357.30h	RETIRE
MANDATORY		L671M3012102 1075	05/18/2016	L671M3012102 (Desc: FORKED LEVER PREASSY.) - (SN#: 1075) : FORKED LEVER PREASSY.	FORKED LEVER PREASSY.	8,700.00H		8,700.00h	7,857.30h	RETIRE
MANDATORY		L671M7001215 793	05/17/2016	L671M7001215 (Desc: BOLT) - (SN#: 793) : BOLT	RETIRE	12,900.00H		12,900.00h	12,057.30h	RETIRE
MANDATORY		L671M7001215 835	05/17/2016	L671M7001215 (Desc: BOLT) - (SN#: 835) : BOLT	RETIRE	12,900.00H		12,900.00h	12,057.30h	RETIRE
MANDATORY		L671M7001220 759	05/18/2016	L671M7001220 (Desc: BOLT) - (SN#: 759) : BOLT 135	RETIRE	8,400.00H		8,400.00h	7,557.30h	RETIRE

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours: 842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings: 1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY		L671M7003210 127	05/18/2016	L671M7003210 (Desc: HINGED SUPPORT) - (SN#: 127) : HINGED SUPPORT 135	HINGED SUPPORT	8,400.00H		8,400.00h	7,557.30h	RETIRE
OPTIONAL		L673M20A1005 00717	05/18/2016	L673M20A1005 (Desc: MAIN ROTOR ACTUATOR) - (SN#: 00717) : ON CONDITION	ON CONDITION	0m				ON CONDITION
MANDATORY		L673M20A1008 00717	05/18/2016	L673M20A1008 (Desc: LONG. AXIS) - (SN#: 00717) : MAIN ROTOR ACTUATOR	OVERHAUL	7,500.00H		7,500.00h	6,657.30h	OVERHAUL
MANDATORY		L673M20A1011 00717	05/18/2016	L673M20A1011 (Desc: LATERAL AXIS) - (SN#: 00717) : MAIN ROTOR ACTUATOR	OVERHAUL	7,500.00H		7,500.00h	6,657.30h	OVERHAUL
MANDATORY		L673M20A1012 00717	05/18/2016	L673M20A1012 (Desc: COLLECTIVE AXIS ACTUATOR) - (SN#: 00717) : MAIN ROTOR ACTUATOR	OVERHAUL	7,500.00H		7,500.00h	6,657.30h	OVERHAUL
MANDATORY		L673M40A1003 00740	05/18/2016	L673M40A1003 (Desc: FENESTRON SERVO ACTUATOR) - (SN#: 00740) : FENESTRON SERVO	OH	7,500.00H		7,500.00h	6,657.30h	OVERHAUL
MANDATORY	Now	0632	05/16/2016	MSM 05-12-00 HYDRAULIC FLUID CHANGE	800 HR // 12 MO HYDRAULIC FLUID CHANGE	800.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	1,633.40h/ 06-24-2016	790.70h/ 2monthOVD	MSM

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.

Advanced Helicopter Services

17986 County Road 94B
Woodland, California 95695
United States

August 24, 2016

Telephone: 530-669-7115

Fax: 530-669-7547

Scan Criteria

Projected Hours: 0.00	Include all items:
Projected Cycles/Landings: 0.00	Include only items due:
Projected Calendar: 0,	Include researched items:
Event Type: ALL	Include non-researched items:
	Include only items that will never display as due:

Config ID number: TrkID-004075

Config item description: EC135P2

Manufacturer: Airbus Helicopters

Model/Part number: EC135P2

Manufactured:

Total Hours:

842.70

Serial Number: 0632

Registration Number: N858WA

Total Cycles/Landings:

1,252.00

Status	Due	Part Number Serial Number	Position Install Date	Event	Event description	Frequency	Last Compliance	Next Compliance	Remaining	Type
MANDATORY	Now	0632	05/16/2016	MSM 05-12-00 LUBRICATION OF DRIVE SHAFT SPLINES OF HYDRAULIC PUMP	LUBRICATION OF DRIVE SHAFT SPLINES OF HYDRAULIC PUMP	800.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	1,633.40h/ 06-24-2016	790.70h/ 2monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-12-00 LUBRICATION OF SWASHPLATE BEARINGS	400 HR // 12 MO LUBRICATION OF SWASHPLATE BEARINGS	400.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	1,233.40h/ 06-24-2016	390.70h/ 2monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-12-00 MAIN TRANSMISSION OIL CHANGE	600 HR // 12 MO MAIN TRANSMISSION OIL CHANGE	600.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	1,433.40h/ 06-24-2016	590.70h/ 2monthOVD	MSM
MANDATORY		0632	05/16/2016	MSM 05-12-00 ROTOR BRAKE FLUID CHANGE	800 HR // 3 YEARS ROTOR BRAKE FLUID CHANGE	800.00H 3y	833.40h/ 1,237.00C/ 06-24-2015	1,633.40h/ 06-24-2018	790.70h/ 1.83year	MSM
MANDATORY	Now	0632	05/16/2016	MSM 05-12-00 TAIL TRANSMISSION OIL CHANGE	400 HR // 12 MO TAIL TRANSMISSION OIL CHANGE	400.00H 12m	833.40h/ 1,237.00C/ 06-24-2015	1,233.40h/ 06-24-2016	390.70h/ 2monthOVD	MSM
MANDATORY	Now	0632	05/16/2016	PERIODICAL INSPECTION 05-24-00	1000 HR / 36 MO	1,000.00H 36m	08-01-2013	1,000.00h/ 08-01-2016	157.30h/ .74monthOVD	INSPECTION
MANDATORY		0632	05/16/2016	STATIC SYSTEM/ ALTIMETER	FAR 91.411	24m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2017	10month	RE-CERTIFY
MANDATORY		0632	05/16/2016	TRANSPONDER CERTIFICATION	FAR 91.413	24m	833.40h/ 1,237.00C/ 06-24-2015	06-24-2017	10month	RE-CERTIFY

*** End of Document ***

" * " Indicates that the item has been researched

Note: This report is provided for planning purposes only and does not supplement or replace the official log books.