
1967 Beech V35 TC Bonanza



Wolfe Aviation

Business Aircraft Acquisitions, Appraisals, Sales and Service

Verlyn Wolfe
Wolfe Aviation

Stockton Metropolitan Airport (KSCK)
2050 East Sikorsky Street, Hangar 7
Stockton, California 95206

P.O. Box 31592, Stockton, California 95213-1592

Telephone: (209) 983-0117 Ext. 233
Fax: (209) 982-5916
Cellular: (209) 607-9804
Email: sales@wolfeaviation.com

Wolfe Aviation believes the following information to be accurate but does not warrant nor guarantee the information accordingly; purchasers should rely upon their own inspection of the aircraft. There shall be no agreement between parties unless set forth in a written contract signed by buyer and seller.

DETAILS:

- Registration: N2728T
- Serial Number: D-8447
- Airframe Time: 4,704 Hours Total Time Since New
- Engine: Teledyne Continental Motors TSIO-520-D, 285 HP
486 Hours Since Major Overhaul; 1,400 Hour TBO
Last Compression Readings: #1 75, #2 73, #3 72, #4 70, #5 76, #6 77
Engine Overhauled by Riddle Flying Service, West Helena, AR 08/02/2005
Crankshaft, Crankcase, Turbo, Controller, Alternator, Fuel Sys. Overhauled
- Propeller: McCauley 3A32C76-5-XLMR/S-82HB-2 Three Blade Prop
486 Hours Since Prop Overhaul; 1,500 Hour TBO
Propeller Overhauled by Mid America Propeller, Wynne, AR 07/26/2005
Prop Governor Overhauled by Aircraft Accessories of Oklahoma 08/02/2005
- Inspection: Annual Inspection Due by 05/01/2019
IFR Recertification Due by 02/01/2018
ELT Battery Replacement Due by 06/01/2020
Oxygen Cylinder Hydrostatic Test Due
Log Books All and Complete
- Damage History: 12/31/2015 Lower Left Skin, Stiffener and Longeron Replaced Due to
Ground Handling Incident
03/12/1982 Left Wingtip, End Rib and Center Wing Skins Replaced
- Price: \$109,000 USD
- Location: Jacqueline Cochran Regional Airport (TRM), Thermal, California

AVIONICS:

- Audio Panel: Collins AMR-350 TSO Audio Panel with 3 LMB
- Coms: Dual Collins VHF-251 Coms
- Navs: Dual Collins VIR-351 Navs
- GPS/VOR/LOC: Collins IND-351A GPS/VOR/LOC/GS Course Deviation Indicator
- GPS #1: Bendix/King KLN 94 TSO Color Moving Map GPS IFR Certified
- MFD/GPS #2: Bendix/King KMD 150 Color Multifunction Display GPS
- Annunciator: Mid-Continent MD41-524 GPS Annunciator
- HSI: Collins 331A-3G Slaved HSI
- DME: Collins TCR-451 DME with IND-451 Control Indicator
- Autopilot: Century III Autopilot with Altitude Hold Coupled to Nav and GPS
- Transponder: King KXP 750 Mode C Transponder with KFS 570 Control Indicator
- Encoding Alt.: Kollsman B45451-10-001 Encoding Altimeter
- Engine Analyzer: JPI EDM-800 Engine Analyzer with Fuel Flow and Data Port
- Intercom: David Clark ISOCOM Four-Place Intercom System with Standard Jacks
- Clock: Wittnauer 8 Day Working Clock
- Vertical Card Compass
- True Airspeed Indicator
- Two-In-One Manifold Pressure and Fuel Flow Indicator
- Auxiliary Power/Lighter Port
- Single Pilot Yoke Control with Push-To-Talk, Electric Trim, Trim Interrupt/Autopilot Disconnect and Map Light Switches
- Electric Trim On/Off Switch
- Avionics Master Switch
- Glove Box

ADDITIONAL FEATURES:

- New Brake Hoses Installed 04/16/2018
- Shimmy Dampener Overhauled 08/22/2017
- Inertia Reel Seat Belts Installed 08/22/2017
- Interior Sound Proofing Insulation Installed 08/22/2017
- New Nose Tire and Tube Installed 08/22/2017
- New Left Wing Fuel Cell Installed 03/08/2017
- New Main Retread Tires Installed 02/02/2016
- New Left Exhaust System Installed 12/31/2015
- Turbocharger Overhauled 12/31/2015
- New Fuel and Oil Hoses Installed 12/31/2015
- New Right Wing Fuel Cell Installed 04/30/2009
- New Aerox Oxygen Cylinder A0053 Installed 08/10/2007
- Overhauled Oxygen Regulator 10/19/2006
- Overhauled Landing Gear Motor Installed 03/01/2005
- Beryl D'Shannon One Piece Windshield Installed 01/23/2003 per STC SA997SO
- Beryl D'Shannon Left and Right Cockpit Windows Installed 01/23/2003 per SRT SA2870WE
- Brackett Air Filter Assembly Installed 05/13/1986 per STC SA71GL
- Cleveland Brake Kit Installed 08/15/1975
- Pilot and Copilot Storm Windows
- Left and Right Aft Cabin Emergency Exit Windows
- Four Port Oxygen System
- Rosen Sun Visors
- Auxiliary Fuel Pump High/Low Settings
- Electric Pitch Trim
- Alternate Static Air Source
- Cabin Heat, Defrost and Air Vents
- Upper and Lower Landing Lights
- Fuselage Strobe Beacon
- Instrument Post Lights
- No Copilot Brakes
- Heated Pitot
- Parking Brake
- Tow Bar
- Engine Inlet Plugs

EXTERIOR:

- Overall White with Blue and Metallic Gold Finish
- Condition 8 (National Aircraft Appraisers Association Exterior Paint Grading Guide)

INTERIOR:

- White Textured Vinyl Headliner with Beige Plastic and Brown Textured Vinyl Trim
- Beige Metal Window Trim
- Beige Textured Vinyl Side Panels
- Beige Textured Vinyl Pilot & Copilot Seats with Seat Cushions, Lapbelts, Shoulder Harnesses and Stowable Center Armrest

-
- Beige Textured Vinyl Aft Cabin Folding Seats with Lapbelts and Stowable Center Armrests
 - Beige Patterned Floor Carpeting with Pilot and Copilot Scuff Mats
 - Overhead Map/Instrument Light
 - Forward Overhead and Lower Air Vents
 - Mid and Aft Cabin Overhead Air Vents
 - Overhead Cabin Speaker
 - Overhead Dome Light
 - Aft Cabin Cargo/Baggage Area with Hat Shelf and Hanger
 - Condition 7 (National Aircraft Appraisers Association Interior Grading Guide)

SPECIFICATIONS:

- Wingspan: 33' 6"
- Length: 26' 5"
- Height: 7' 7"
- Gross Weight: 3,400 lbs.
- Useful Load: 1,057 lbs. Actual
- Fuel Capacity: 80 gals Optional Fuel System (74 gals Usable)

FINANCIAL OPTIONS:

- 10% to 20% Down Payment
- 4.65% to 4.95% Rate
- Up to 20 Year Term
- Fully Amortized