
1974 Piper PA-34-200 Seneca



Wolfe Aviation

Business Aircraft Acquisitions, Appraisals, Sales and Services

Verlyn Wolfe, PSCA

ASA Accredited Senior Appraiser

Wolfe Aviation

Stockton Metropolitan Airport (KSCK)

2050 East Sikorsky Street, Hangar 7

Stockton, California 95206

P.O. Box 31592, Stockton, California 95213-1592

Telephone: (209) 983-0117 Ext. 233

Cellular: (209) 607-9804

Email: sales@wolfeaviation.com

Wolfe Aviation believes the following information to be accurate but does not warrant nor guarantee the information accordingly; purchasers should rely upon their own inspection of the aircraft. There shall be no agreement between parties unless set forth in a written contract signed by buyer and seller.

Details:

- Registration: N43130
- Serial Number: 34-7450180
- Airframe Time: 7,370 hours total time since new
- Left Engine: Lycoming IO-360-C1E6, 200 HP, serial #: RL-9371-51
460 hours SMOH; 2,000 hour TBO
Overhauled by Gill's Aircraft Engines, Reno, NV 06/05/2007
Compressions at last annual: #1 77, #2 77, #3 76, #4 72
- Right Engine: Lycoming LIO-360-C1E6, 200 HP, serial #: RL-422-67A
1,353 hours since IRAN insp. Gill's Aircraft Engines, Reno, NV 09/25/2004
1,841 hours SMOH; 2,000 hour TBO
Overhauled by Mid Valley Aviation, Los Banos, CA 04/24/2002
Compressions at last annual: #1 75, #2 76, #3 78, #4 78
- Left Propeller: Hartzell HC-C2YK-2CEGUF/FC7666A-2, serial #: AU9556B
1,311 hours since propeller repair/reseal by American Prop. Svc.12/17/2007
2,289 hours SPOH; 2,000 hour TBO
Propeller overhauled by American Propeller Service 12/13/2000
- Right Propeller: Hartzell HC- C2YK -2CLGUF/FJC7666A, sn: AU10311B
825 hours SPOH; 2,000 hour TBO
Propeller overhauled by American Propeller Service 09/27/2004
- Inspection: Annual inspection due 06/01/2022
IFR recertification due 12/01/2023
ELT battery replacement next due 04/30/2023
First A/F logbook destroyed in office fire, A/F entries commence 02/01/1983
- Repairs: Left wing wheel well repairs 09/26/2005 (see Form 337)
L/R lower nacelle skin & wing rib flanges repairs 11/20/2003 (see Form 337)
Right wing rib and skin repair, Piper Kit 369 installed 03/01/1994
- Price: \$115,000 USD
- Location: Stockton Metropolitan Airport (SCK), Stockton, California

Avionics & Instrumentation:

- Audio Panel: Garmin GMA 340 digital audio panel with 3LMB
- Nav/Com/GPS: Garmin GNS 430 WAAS Nav/Com/GPS
- Nav/Com: Bendix/King KX 155 TSO Nav/Com
- GPS/VOR/LOC: Garmin GI 106A GPS/VOR/LOC precision course deviation indicator
- VOR/LOC: Bendix/King KI 203 VOR/LOC course deviation indicator
- Autopilot: None
- Transponder: Garmin GTX 335 ADS-B Out transponder
- ADS-B In/Out: Garmin GTX 335 ADS-B Out transponder
- EGT: Analog single probe engine EGT indicator
- ICS: Six place intercom standard jacks via Garmin GMA 340 audio panel
- Clock: Wakmann 8-Day clock
- Hour Meter: Hobbs recording hour meter
- ELT: Battery replacement next due 04/30/2023
- True airspeed indicator
- Windshield OAT probe and indicator
- Lighter/auxiliary power port
- Pilot control yoke with electric trim and PTT switches

-
- Copilot control yoke PTT switch

Additional Features:

- Rosen sun visors
- Overhauled attitude indicator installed 09/01/2021
- New engine control quadrant cover installed 02/15/2018
- Nose and main tires replaced with new 01/06/2017
- Brackett Air Filters installed 04/06/2002 per STC SA693CE
- Bogert Aviation copper elect. cables installed 04/26/2001 per STC SA3531NM & PSB 836A
- External ground power receptacle
- Aux fuel pumps
- Nose baggage compartment left side accessible
- Rudder and elevator trim
- Alternate static air source
- Heated pitot static head
- Pilot cockpit storm window
- Landing lights, wingtip strobe lights, horizontal stabilizer red beacon strobe
- Parking brake
- Tow bar

Exterior:

- Aircraft refinished by Nice Air repair station #NZDR287K 11/14/2019
- Overall White with gray N number
- Condition 7 (Professional Aircraft Appraisal Organization Exterior Paint Grading Guide)

Interior:

- Interior carpet and seats refurbished 2021
- White textured vinyl and plastic headliner
- White textured plastic window trim
- Blue vinyl over blue carpeting side panels
- Pilot and copilot gray textured vinyl seats with shoulder harnesses and lap belts
- Mid cabin folding gray textured vinyl seats lap belts
- Aft cabin folding gray textured vinyl seats lap belts
- Blue floor carpeting
- Overhead cabin speaker
- Overhead dimming pilot and copilot map lights
- Mid and aft cabin overhead switchable spot lights
- Aft cabin cargo/baggage area with eyelet and hat shelf
- Condition 7 (Professional Aircraft Appraisers Organization Interior Grading Guide)

Specifications:

- Wingspan: 38' 11"
- Length: 28' 8"
- Height: 9' 11"
- Gross Weight: 4,200 lbs.
- Useful Load: 1,286.0 lbs. actual
- Fuel Capacity: 98 gals (93 usable gals)