
1988 Piper PA-46-310P Malibu 2001 JetPROP DLX



Wolfe Aviation

Business Aircraft Acquisitions, Appraisals, Sales and Service

Verlyn Wolfe

Wolfe Aviation

Stockton Metropolitan Airport (KSCK)
2050 East Sikorsky Street, Hangar 7
Stockton, California 95206

P.O. Box 31592, Stockton, California 95213-1592

Telephone: (209) 983-0117 Ext. 233

Fax: (209) 982-5916

Cellular: (209) 607-9804

Email: verlyn@wolfeaviation.com

Wolfe Aviation believes the following information to be accurate but does not warrant nor guarantee the information accordingly; purchasers should rely upon their own inspection of the aircraft. There shall be no agreement between parties unless set forth in a written contract signed by buyer and seller.

Details:

- Registration: N788SM
- Serial Number: 4608116
- Airframe: 2,848 hours total time since new
- Engine: Manufacturer: Pratt & Whitney Canada
Model number: PT6A-34, 560 HP
Serial number: PCE-RB0155
Manufacture date: 10/26/2001
Total time since new: 1,309 Hours
HSI interval: N/A, due to trend monitoring since new
Time since HSI: N/A, due to trend monitoring since new
Time to overhaul: 2,691 Hours
TBO interval: 4,000 Hours, with trend monitoring s/new
- Propeller: Manufacturer: Hartzell, four blade reversible
Model number: HC-E4N-31/E8501B-3.5
Serial number: HH-1365
Manufacture date: Late 2001
Reseal/repair date: 04/12/2012
Hours since reseal/repair: 475.8 Hours
Total time since new: 1,309 Hours
TBO interval: 4,500 Hours
- Inspections: Annual inspection due 08/01/2021
IFR recertification due 08/01/2022
ELT battery replacement due 12/31/2020
- Damage: No damage history
- Records: First airframe logbook to 23.6 hours missing; otherwise, complete and continuous logbooks, and records
- Price: \$785,000 USD
- Location: Stockton Metropolitan Airport (KSCK), Stockton, California

Additional Features:

- Low time aircraft in beautiful condition
- New Rapco vacuum air pump installed 09/23/2016
- Freon air conditioning system equipment serviced 03/29/2016
- Left and right main landing gear trunnion bushings replaced 02/05/2015
- Beta feedback carbon block assembly replaced 02/05/2015
- Pilot's instrument panel fabricated to accommodate Garmin upgrades 12/06/2013
- Rocket Engineering airframe and turbine engine modifications installed 12/13/2001 per STC ST00541SE, with gross weight increase mod
- V.K. Leasing auxiliary fuel tank fuel caps installed 12/13/2001 per STC SA00859AT
- Nordam pilot's heated windshield installed 04/16/1998 per STC SA095354SC
- Certified for flight into known icing, surface deice boots, ice lights, and ice door
- Standby vacuum system
- Standby alternate static air
- External ground power receptacle

Avionics & Instruments:

- Audio panel: Garmin GMA 340 digital audio panel with 3LMB
- Nav/Com/GPS1: Garmin GTN 750 touchscreen Nav/Com/GPS
- Nav/Com/GPS2: Garmin GTN 750 touchscreen Nav/Com/GPS
- GPS/VOR/LOC: Bendix/King KI 206 GPS/VOR/LOC course deviation indicator
- EFIS:
 - Garmin G500 dual-screen electronic flight display
 - Garmin GDU 620 primary function and multifunction displays
 - Garmin GDC 74A air data computer
 - Garmin GRS 77 attitude heading reference system
 - Garmin GMU 44 magnetometer
 - Garmin GTP 59 outside air temperature probe
 - Garmin GAD 43E autopilot adapter
- Autopilot/FD: King KFC 150 digital flight control system with flight director
- AP computer: Bendix/King KC 192 autopilot flight computer module
- Yaw dampener: Yaw dampener panel mounted switch
- Roll steering: DAC GDC31 roll steering converter
- Annunciator: Autopilot source annunciator switch
- ADF: Bendix/King KR 87 TSO ADF
- Standby att.: Mid-Continent Instruments MD302 color standby attitude indicator
- Compass Sys.: Copilot Bendix/King KCS 55A compass system
 - King KI 525A HSI
 - Bendix/King KI 256 flight command indicator
 - Bendix/King KG 102A directional gyro
 - Bendix/King KA 51B slave meter
- Transponders: Dual Garmin GTX 330ES Mode S transponders with ext. squitter
- TCAS: BF Goodrich Skywatch traffic collision avoidance system
- Stormscope: BF Goodrich WX-500 Series II Weather Mapping Sensor stormscope
- ADS-B: Garmin GDL 88 ADS-B transceiver with traffic/weather interface
- Data link: Garmin GDL 69A satellite weather/entertainment audio data link
- Remote control: Garmin GRT 10/GRC 10 SiriusXM wireless transceiver/remote control
- Trend monitor: Shadin engine trend monitoring system
- ELT: Artex ME-406 emergency locator transmitter with panel switch & ind.
- Chronometer: Mid-Continent Instruments MD93 pilot digital clock/dual USB charger
- Auxiliary power: Dual copilot USB power ports
- Ground com: Ground clearance com switch
- ICS: Six place intercom system with music mute & aux/XM switches, aux in and emergency com ports
- Davtron M450 D.C. digital voltage indicator
- Electronics International digital volts and amps indicator
- Hobbs recording hour meter
- Pilot yoke electric trim, trim interrupt, autopilot disconnect, course wheel steering and ident switches
- Copilot yoke PTT switch

Exterior:

- Original factory paint scheme
- Upper white over tan with blue and red trim and accents
- Forward left side airframe external baggage/storage locker
- Condition 7 (Professional Aircraft Appraisal Organization exterior rating guide)

Interior:

- Interior reupholstered 12/18/2014 by Elite Air Interiors, Mather, California
- Six place executive interior (two crew and four passengers; three passenger seats shown, fourth seat in original blue leather covering included, not shown)
- Ultra Leather Silver Pearl headliner and upper window trim
- Space Moon Fabric cabin window curtains
- Ultra Leather Silver Pearl upper sidewall panels with Avion Rouge Leather trim, and Aviator Winesap carpet lower sidewall panels
- Leather Avion Sterling sidewall rails
- Pilot and copilot Leather Avion Sterling seats with shoulder harnesses, lap belts, stowable center armrests
- Silver gray instrument panel
- Four place club configuration (three of four seats shown) Leather Avion Sterling cabin seats with headrests, stowable center armrests, shoulder harnesses and lap belts
- Stowable right side cabin executive writing table
- Aviator Winesap floor carpeting
- Overhead switchable position seat lights at all seats
- Overhead position air vents at all seats
- Cup holders at all seats
- Cabin entry courtesy light
- Spacious aft internal baggage/storage compartment area
- Condition 8 (Professional Aircraft Appraisal Organization interior rating guide)

Specifications:

- Cabin: Passengers: 4, Crew: 2
- Exterior: Wingspan: 43' 0"
Length: 28' 4"
Height: 11' 2"
- Gross weight: 4,318 lbs.
- Useful load: 1,282.2 lbs.
- Fuel capacity: 152 gals. (150 gals. usable)