1994 Beechcraft F33A Bonanza



Wolfe Aviation

Business Aircraft Acquisitions, Appraisals, Sales and Service

Verlyn Wolfe, PSCA ASA Accredited Senior Appraiser Wolfe Aviation

Stockton Metropolitan Airport (KSCK) 2050 East Sikorsky Street, Hangar 7 Stockton, California 95206

P.O. Box 31592, Stockton, California 95213-1592

Telephone: (209) 983-0117 Mobile: (209) 607-9804

Email: sales@wolfeaviation.com

Wolfe Aviation believes the following information to be accurate but does not warrant nor guarantee the information accordingly; purchasers should rely upon their own inspection of the aircraft. There shall be no agreement between parties unless set forth in a written contract signed by buyer and seller.

Details:

Registration: N1523P

Serial number: CE-1769 (last year of manufacture)

• Background: This beautiful, very low time, nearly original condition F33A Bonanza with no

damage history has been well taken care of by its three end user owners since new. The aircraft has a past and present pedigree of expert Beechcraft maintenance. The current owner has owned N1523P since June of 2013. The exterior finish cosmetically is in remarkably good

condition with few flaws on the leading-edge surfaces (see the 62 close-up high-resolution photos for greater details). This is an amazing opportunity to own a last year of manufacture F33A Bonanza in near original condition to keep and fly as is, upgrade to a TCM IO-550 engine, and or upgrade the

avionics to a modern Garmin suite.

• Airframe time: 1,696 hours total time since new

Engine: Continental IO-550-BB sn: 578957, 285 HP

1,696 hours since new; 591 hours since top O/H 04/20/2014; 1,700 hr TBO Compressions at last annual: #1 64, #2 70, #3 70, #4 50, #5 68, #6 75 500 Hour magneto inspections performed 06/20/2016 @ 1,224.6 hours ETT

• Propeller: McCauley 3A32C406-C-G-82NDB-2 Three blade const. speed, sn: 922059

411 hours since prop reseal, 780 hours since prop O/H; 1,200 hour TBO Prop resealed by America Propeller Service, Redding, CA 07/14/2017 Prop overhauled by AAR Aircraft Services, Oklahoma City, OK 12/22/2006

Inspection: Annual inspection due 03/01/2025

IFR recertification due 08/01/2025

ELT battery replacement due 04/30/2025

Logbooks: All original and complete

Damage: No damage historyPrice: \$295,000 USD

Location: Stockton Metropolitan Airport (SCK), Stockton, California

Avionics:

Audio panel: Bendix/King KMA 24 TSO audio panel
 GPS #1: Bendix/King KLN 90A GPS (intermittent)

GPS #2: Garmin aera 796 touchscreen GPS w/charts, traffic, weather, yoke mounted

Nav/Com #1: Bendix/King KX 155 TSO Nav/Com
 Nav/Com #2: Bendix/King KX 155 TSO Nav/Com

VOR/LOC: King KI 208 VOR/LOC course deviation indicator

Compass Sys.: King KCS 55A compass system

King KI 525A HSI

KG 102A Directional Gyro KA 51B Slave Meter

ADF: Bendix/King KR 87 ADF receiver with KI 228 indicator
 DME: Bendix/King KN 63 DME with KDI 572 display control
 Autopilot: Bendix/King KFC 150 autopilot with flight director

Transponder: Garmin GTX 345 ADS-B In/Out transponder
 ADS-B: Garmin GTX 345 ADS-B In/Out transponder

Encoder: Trans Cal Ind. SSD120-35C-RS232 remote encoder

Encoding Alt.: Bendix/King KEA 130 encoding altimeter with mb and IN. Hg indicators

CHT/EGT: Single probe CHT and EGT analog indicators

ELT: Artex 110-4 ELT

Chronometer: Beechcraft/Davtron panel mounted guartz chronometer

Hour Meter: Datcon hour meter

ICS: NAT Intervox four place intercom system with Telex ANR pilot and copilot

jacks and four standard jacks

OAT: Beechcraft Aerotherm free air temperature indicator

Lighter/auxiliary power port

Pilot yoke electric trim, AP disconnect/trim interrupt, CWS, ident, map light and PTT switches

Copilot PTT switch

Additional Features:

• Excellent maintenance pedigree

- New left exhaust muffler installed 02/01/2024
- New left main gear uplock cable installed 02/01/2024
- New elevator rod ends installed 02/01/2024
- Overhauled alternator installed 04/04/2023
- Landing gear actuator overhauled 01/25/2023
- Landing gear motor overhauled 11/02/2020
- Brake discs and pads replaced 10/03/2019
- Rapco instrument air pump installed 08/13/2019
- New main tires installed 06/18/2019
- KI 256 flight command indicator overhauled 09/05/2018
- All four fuel transmitters overhauled 11/11/2014
- Dual control yokes
- Left and right aft cabin emergency windows
- Fire extinguisher mounted aft of copilot seat on cabin floor
- Pilot storm window
- Manual cowl flaps
- Aux fuel pump
- Alternate static air source
- Vent blower
- Wingtip strobe lights
- Strobe beacon
- External ground power receptacle
- Heated pitot
- Copilot brakes
- Parking brake

Exterior:

- Original factory finish
- Overall Ivory (U4631) with Adobe (U4379) and Sable Brown (U4394) trim and accents
- Large external baggage compartment door
- Condition 7 (Professional Aircraft Appraisal Organization Exterior Paint Grading Guide)

Interior:

- Refurbishment of headliner, aft panel and sun visors by Elite Air Interiors 12/20/2016
- Tapis Pale Beige Ultraleather headliner

- Off white plastic window trim
- Adobe textured vinyl with brown textured vinyl trim over beige carpeting side panels
- Pilot and copilot brown textured vinyl seats with fabric inserts, headrests, lap belts, shoulder harnesses and stowable center armrest (copilot seat fabric torn on seatback and seat cushion)
- Aft cabin two place brown textured vinyl seats with fabric inserts, headrests, lap belts, and stowable center armrest (excellent condition)
- Switchable overhead cabin lights at all seats
- Overhead cabin speaker
- Forward cabin upper and lower air vents
- Aft cabin upper air vents
- Beige floor carpeting
- Spacious aft cabin cargo/baggage area with hat shelf and clothes hanger
- Condition 7 (Professional Aircraft Appraisal Organization Interior Grading Guide)

Specifications:

Wingspan: 33' 6"
Length: 26' 8"
Height: 8' 3"
Gross weight: 3,400 lbs.

Useful load: 1112.95 lbs. actual
Fuel capacity: 80 gals (74 gals usable)